Well Condition Observations and Video Log Inspection of Groundwater Monitoring Well MW-44-125

PG&E Topock Compressor Station, Needles, California

Date: April 14, 2006

Introduction

This technical memorandum describes the well construction, current well conditions, and results of field observations and inspection of groundwater monitoring well MW-44-125, recently installed at the Pacific Gas and Electric Company (PG&E) Topock Compressor Station. Well MW-44-125 is deepest well in a cluster of three groundwater monitoring wells installed in the floodplain area of the Topock site as part of PG&E's 2006 Interim Measures (IM) performance monitoring drilling program (see Figure 1 for the MW-44 cluster location). The California Department of Toxic Substance Control (DTSC) is the lead regulatory agency overseeing the IM drilling and performance monitoring program.

This purpose of this memorandum is to document the current conditions and results for the video log inspection of MW-44-125 and to present recommendations for ongoing monitoring, evaluation, and maintenance of this well.

Current Well Conditions and Field Observations

Well Installation and Development

Well MW-44-125 is a 2-inch diameter PVC monitoring well that was initially installed on February 26, 2006 in a "nested" well completion (two wells in a single borehole). During well construction, the shallow portion of the deeper well was damaged. On March 6-7, MW-44-125 and paired shallower nested well screen (MW-44-70) were successfully re-installed. Figure 2 presents a well construction details for MW-44-125 and the shallower well installed in the MW-44 nested well completion.

Well MW-44-125 was developed initially on March 8 by bailing, surging, and pumping. During development, it was noted that the well's 10-foot blank casing section (sump) below the well screen had filled-in with material, believed to be a mixture of filter-pack sand and formation sediment. The sediment in the bottom of the well was bailed and air-lifted out. Upon completion of development, sand/sediment had filled the sump interval to approximately 2 feet below the well screen (see Figure 2). On March 16, crews re-developed well MW-44-125 by bailing, surging, and pumping. Well soundings during re-development confirmed soft-bottom well depths ranging from 125.1 to 128.9 feet below top of casing. Table 1 summarizes the MW-44-125 well development activities and the field measurements.

Well Purging and Sampling Observations

Well MW-44-125 was initially purged and sampled on March 9. This well has been subsequently sampled on March 23 and April 4 (bi-weekly sampling schedule) in accordance with DTSC direction. Table 1 summarizes the well conditions, purging details, and characteristics of the groundwater samples collected during the first three sampling events at MW-44-125. The well depth measurements shallower than construction depth suggested that a breach in the well casing is allowing filter-pack sand and/or formation sediment to enter the well casing.

It should be noted that, although the purge rate for this well is lower than comparable depth monitoring wells (0.5 gallons per minute [gpm] versus typical 1-2 gpm purging rates), the field parameter readings for turbidity and specific conductance are representative and consistent with groundwater samples collected from equivalent wells in the floodplain area (see PG&E's groundwater monitoring reports). In addition to measuring static water level and field parameters, well bottom depths were sounded March 22 and will continue to be measured during ongoing groundwater sampling.

Video Log Inspection

To better assess the condition of the well, a video log inspection of MW-44-125 was performed on March 28, 2006 by Welenco, Inc. A 1-5/8 inch diameter color video camera was lowered into the well to inspect the condition of the PVC casing and screen. Kate Burger of DTSC was on site to observe the well video survey. The video output was viewed going into and out of the well.

The video showed that all of the threaded joints in the blank casing and screen were intact. No breaks or other damage to the blank casing or well screen were visible. The well screen slots, from 115 to 125 feet below ground surface, were intact. The top of the sediment in the well sump was visible at 128 feet, approximately 3 feet below the lowest screen slots. The well video log report and images from the inspection are attached to this memorandum.

Conclusions and Recommendations

Based on the results of the video log survey, it appears that a casing breach or parting occurred most likely at the bottom cap of the well casing during well construction, and that filter-pack sand and/or formation sediment has filled the bottom approximate 7 feet of the well sump. This cannot be confirmed or refuted by video or geophysical methods. The video log does indicate the well screen and blank casing above the screen have not been damaged or cracked. The most recent field purging measurements (April 4 sampling) indicate that MW-44-125, in its current condition is a functioning well, is capable of providing low turbidity groundwater samples that are representative of water quality in the aquifer zone monitored at this location.

PG&E recommends the following course of action regarding well MW-44-125:

• Continue routine sampling of the well in its current condition. The well bottom depth will be measured before and after purging to assess if the column of sediment in the well sump remains stable or increases with purging and over time.

- The field sampling data sheet for well MW-44-125 (Table 1) will be maintained and updated with well depth and other field measurements during ongoing monitoring. The field sampling data sheet will be provided to DTSC monthly for review.
- If the column of sediment in the well sump remains stable during continued sampling and water quality parameters remain consistent with water quality data from nearby wells monitoring an equivalent aquifer interval, then no further action is recommended.
- If the column of sediment in the well sump increases with purging and over time or if unusual inconsistencies are observed in water quality parameters, abandonment, repair and replacement options will be further evaluated, in consultation with DTSC. One available option is lining the well with a 1.5-inch diameter well screen and casing. The re-lined well screen interval would be equivalent to MW-44-125 but a smaller slot size (e.g., 0.010-inch) would be considered. The smaller diameter well can be purged and sampled with a Whale-brand (or equivalent) 12-volt submersible pump. If required, a dedicated Whale-pump would be installed in MW-44-125.

PG&E will update DTSC on a routine basis of the results of field measurements and observations from the continued sampling of MW-44-125. Crews will be prepared to implement the above actions as part of the site groundwater monitoring well maintenance program.

Certification

This technical memorandum was prepared by CH2M HILL under the supervision of the professional whose seal and signature appears hereon, in accordance with currently accepted professional practices; no warranty, expressed or implied, is made.

Paul Betty

Paul Bertucci, Certified Engineering Geologist #1977





BAO \\ZINFANDEL\PROJ\PACIFICGASELECTRICCO\TOPOCKPROGRAM\GIS\MXD\2006\PMP_WELLS_SECTIONS_8X11M.MXD PMP_WELLS_SECTIONS_8X11M.PDF 4/10/2006 13:48:58



TABLE 1	
Well Development and Sampling Summary	- Floodplain Well MW-44-125
PG&E Topock 2006 IM Performance Monitor	ring

Date	Activity	Static Water Level (ft BTOC)	Pre-Pumping Sounded Well Depth (ft BTOC)	Post-Pumping Final Well Depth (ft BTOC)	Remarks	Purge Rate (gpm)	Total Volume Purged (gallons)	Final Turbidity (NTU)	Field Specific Conductance (µS/cm)
8-Mar-06	Initial well development	17.96	128.67			1 to 2.3	198	9	12,100
9-Mar-06	Sampling event #1	19.10				0.2 to 1	24	293	13,500
16-Mar-06	Second well development	18.25	129.11	128.80	soft bottom	0.4	44	136	18,900
17-Mar-06	Well sounding	17.86	128.78	128.78					
18-Mar-06	Well sounding	18.04	128.75	128.75					
22-Mar-06	Sampling event #2	18.20	128.90	128.90		0.4	57	1	15,000
5-Apr-06	Sampling event #3	16.29				0.5	60	5	15,600
14-Apr-06	Well sounding	16.58	128.8						

NOTES:

1. All water level and sounded well depths in feet below top of casing (ft BTOC).

2. MW-44-125 top of casing datum is 1.38 feet above ground surface. See Figure 2 for MW-44-125 well construction details.

3. Purge rates in gallons per minute (gpm) rounded off to 0.1 gpm. (--) denotes data not collected or available.

Vid-	Pac	Welll	oore Vide	eo Report]welenco			
Company Address City Requested by	CH2MHILL 2285 Corporate Henderson Jay Piper	e Circle #200	StateN	Zip 89074	Job Ticket Well No Survey Date Well Owner	5894 Run No. 1 44-125		
Copy To _ Reason For Su Operator _	irvey <u>Lool</u> Mitch Tullis	king For Breaks	Well	Depth	Camera Zero Datum Video Vai	1 5/8" Rental Color Camera Top of Casing P-03		
Location Casing I.D. at	Topock Site Surface 2'	I.D. Refere	ence	Well Records	Build-Up	None		
SELECTED WELLBORE SNAPSHOTS			TRUE DEPTHS		WELLBORE	CASING INFORMATION		
0000'	0016' (See Other Side)	0'	Recordings Start - Ze	croed at Top of Casi	ng, 1' Above GL		
000077	00113		16'	Static Water Level	0-04394 (Arabii) (2007-0342 - Mr. Profie			
		Carlos A	65'	Joint				
			116'	Top of Perforations.	Horizontal Slots, Sc	reen		
0065'	0116'	See Other Side)	125'	Bottom of Perforation	ns, Slots			
Canal Pr			126'	Joint				
		and the second second	128'	Fill, Bottom of well				
				end of survey				
0125! (See Other	Side) 0126							
-0.6977								
0128' (See Other	Side)							
welenco, inc. 5201 Woodmere Bakersfield, CA	ww e-n 93313 Ph Fax	ww.welenco.com nail: welenco@wele one: 1-(800) 445-99 x: 1-(661) 834-2550	enco.com 14	lotes: Mobile Sy	vstem used in Floc	odplain		

welenco, inc. 5201 Woodmere Dr. Bakersfield, CA 93313

www.welenco.com e-mail: welenco@welenco.com Phone: 1-(800) 445-9914 Fax: 1-(661) 834-2550

Mobile System used in Floodplain Notes:













0128'