

State of California STATE WATER RESOURCES CONTROL BOARD



2016-2017 ANNUAL REPORT FOR STORM WATER DISCHARGES ASSOCIATED WITH INDUSTRIAL ACTIVITIES

Reporting Period July 1, 2016 through June 30, 2017

Retain a copy of the completed Annual Report for your records.

Please remember that a Notice of Termination and new Notice of Intent are required whenever a facility operation is relocated or changes ownership.

If you have any questions, please contact your Regional Board Industrial Storm Water Permit Contact. The names, telephone numbers, and e-mail addresses of the Regional Board contacts, as well was the Regional Board office addresses, can be found at: http://www.waterboards.ca.gov/water_issues/programs/stormwater/contact.shtml

General Information

A. Facility Information

WDID: 7 36I019443

Business Name: PGE Topock Interim Measure No 3Physical Address: I 40 and Park Moabi RdCity: NeedlesContact Person: Chris SmithState: CAPhone: 760-258-7899Zip: 92363Email: cks5@pge.comOten dend in destrict Olegei faction (OLO) On deep 1050 P. for the last of the last of

Standard Industrial Classification (SIC) Codes: 4953-Refuse Systems

B. Facility Owner Information

Business Name: Pacific Gas Electric CoMailing Address: PO Box 337City: NeedlesContact Person: Christopher SmithState: CAPhone: 760-258-7899Zip: 92363Email: cks5@pge.com

C. Facility Billing Information

Business Name: Pacific Gas Electric Company San FranciscoMailing Address: PO BOX 337City: NeedlesContact Person: Glen Curtis RussellState: CAPhone: 760-791-5884Zip: 92363Email: gcr4@pge.com

JOAQUIN ESQUIVEL, CHAIR | EILEEN SOBECK, EXECUTIVE OFFICER





Question Information

1. Has the Discharger conducted monthly visual observations (including authorized and unauthorized Non-Storm Water Discharges and Best Management Practices) in accordance with Section XI.A.1?



No

If No, see Attachment 1, Summary of Explanation.

2. Has the Discharger conducted sampling event visual observations at each discharge location where a sample was obtained in accordance with Section XI.A.2?



X No

If No, see Attachment 1, Summary of Explanation.

3. Did you sample the required number of Qualifying Storm Events during the reporting year for all discharge locations, in accordance with Section XI.B?

Yes

IXI No

If No, see Attachment 1, Summary of Explanation.

4. How many storm water discharge locations are at your facility?

5

5. Has the Discharger chosen to select Alternative Discharge Locations in accordance with Section XI.C.3?

Yes



6. Has the Discharger reduced the number of sampling locations within a drainage area in accordance with the Representative Sampling Reduction in Section XI.C.4?





6.1. Has the Discharger reduced the frequency of sampling at the facility area in accordance with the Sample Frequency Reduction in Section XI.C.7?





JOAQUIN ESQUIVEL, CHAIR | EILEEN SOBECK, EXECUTIVE OFFICER





7. Permitted facilities located within an impaired watershed must assess for potential pollutants that may be present in the facility's industrial storm water discharge. Using the table below, populated based on the facility's location, indicate the presence of the potential pollutant at the facility.

The facility is not located within an impaired HUC 10 watershed. You are not required to select any Industrial Pollutants. Skip Questions 8 and 9.

8. Has the Discharger included the above pollutants in the SWPPP pollutant source assessment and assessed the need for analytical monitoring for the pollutants?

\times	Yes
----------	-----

	No
--	----

If No, what date will the parameter(s) will be added to the SWPPP and Monitoring Implementation Plan?

9. Were all samples collected in accordance with Section XI.B.5?

Yes	
-----	--



If No, see Attachment 1, Summary of Explanation.

10. Has any contained storm water been discharged from the facility this reporting year?





If Yes, see Attachment 1, Summary of Explanation.

11. Has the Discharger conducted one (1) annual evaluation during the reporting year as required in Section XV?



No

If Yes, what date was the annual evaluation conducted? 05/04/2017

If No, see Attachment 1, Summary of Explanation.

JOAQUIN ESQUIVEL, CHAIR | EILEEN SOBECK, EXECUTIVE OFFICER





12. Has the Discharger maintained records on-site for the reporting year in accordance with XXI.J.3?



No

If No, see Attachment 1, Summary of Explanation.

If your facility is subject to Effluent Limitation Guidelines in Attachment F of the Industrial General Permit, include your specific requirements as an attachment to the Annual Report (attach as file type: Supporting Documentation).

ANNUAL REPORT CERTIFICATION

I certify under penalty of law that this document and all attachments were prepared under the direction or supervision in accordance with a system designed to assure that qualified personnel propoerly gether and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Printed Name: Glen Russell

Title: Site Operations Manager

Date: 07/05/2017

2016-2017

Annual Report for WDID 7 36I019443

Summary of Explanations

1, 2016 through June 30, 2017 period; therefore, no stormwater samples were collected. In general, discharge of stormwater from the facility did not occur due to the arid climate, drainage properties of soil at unpaved areas, and pumping of storm water collected on the concrete treatment pad into the treatment facility. During rain events, when safe, the site was walked to observe and monitor discharge locations. Question 3 There were no storm events that resulted in discharge of stormwater from the site during the July 1, 2016 through June 30, 2017 period; therefore, no stormwater samples were collected. In general, discharge of stormwater from the facility did not occur due to the arid climate, drainage properties of soil at unpaved areas, and pumping of storm water collected on the concrete treatment pad into the treatment facility. During rain events, when safe, the site was walked to observe and monitor discharge locations. Question 9 There were no storm events that resulted in discharge of stormwater from the site during the July 1, 2016 through June 30, 2017 period; therefore, no stormwater from the site during the July 1, 2016 through June 30, 2017 period; therefore, no stormwater from the site during the July 1, 2016 through June 30, 2017 period; therefore, no stormwater from the site during the July 1, 2016 through June 30, 2017 period; therefore, no stormwater from the site during the July 1, 2016 through June 30, 2017 period; therefore, no stormwater collected on the concrete treatment pad into the treatment facility. During rain events, when safe, the site was walked to observe and monitor discharge locations. Question 9 There were no storm events that resulted in discharge of storm water collected on the concrete treatment pad into the treatment facility. During rain events, when safe, the site was walked to observe and mo	Explanation Question	on	Explanation Text	Explanation Text				
1, 2016 through June 30, 2017 period; therefore, no stormwater samples were collected. In general, discharge of stormwater from the facility did not occur due to the arid climate, drainage properties of soil at unpaved areas, and pumping of storm water collected on the concrete treatment pad into the treatment facility. During rain events, when safe, the site was walked to observe and monitor discharge locations. Question 9 There were no storm events that resulted in discharge of stormwater from the site during the July 1, 2016 through June 30, 2017 period; therefore, no stormwater samples were collected. In general, discharge of stormwater from the facility did not occur due to the arid climate, drainage properties of soil at unpaved areas, and pumping of storm water collected on the concrete treatment pad into the treatment facility. During rain events, when safe, the site was walked to observe and monitor discharge locations. Question 9 Summary of Attachments	Question 2		1, 2016 through Ju general, discharge properties of soil a treatment pad into	1, 2016 through June 30, 2017 period; therefore, no stormwater samples were collected. In general, discharge of stormwater from the facility did not occur due to the arid climate, drainage properties of soil at unpaved areas, and pumping of storm water collected on the concrete treatment pad into the treatment facility. During rain events, when safe, the site was walked to observe and monitor discharge locations.				
1, 2016 through June 30, 2017 period; therefore, no stormwater samples were collected. In general, discharge of stormwater from the facility did not occur due to the arid climate, drainage properties of soil at unpaved areas, and pumping of storm water collected on the concrete treatment pad into the treatment facility. During rain events, when safe, the site was walked to observe and monitor discharge locations. Summary of Attachments	Question 3		general, discharge of stormwater from the facility did not occur due to the arid climate, drainage properties of soil at unpaved areas, and pumping of storm water collected on the concrete treatment pad into the treatment facility. During rain events, when safe, the site was walked to					
	Question 9 There were no storm events that resulted in discharge of stormwater from the site during the 1, 2016 through June 30, 2017 period; therefore, no stormwater samples were collected. In general, discharge of stormwater from the facility did not occur due to the arid climate, drain properties of soil at unpaved areas, and pumping of storm water collected on the concrete treatment pad into the treatment facility. During rain events, when safe, the site was walked					ples were collected. In the arid climate, drainage ected on the concrete		
			Summar	y of Attachments	Devi Nevel en			

	Attachment Type	Attachment Title	Description	Date Uploaded	Part Number	Attachment Hash
--	-----------------	------------------	-------------	---------------	-------------	-----------------

2016-2017

Annual Report for WDID 7 36I019443

List of Identified Pollutants within the Impaired Watershed Pollutant Present at Facility?

Parameter