



2017-2018  
**ANNUAL REPORT**  
FOR STORM WATER DISCHARGES  
ASSOCIATED WITH INDUSTRIAL ACTIVITIES

Reporting Period July 1, 2017 through June 30, 2018

**Retain a copy of the completed Annual Report for your records.**

Please remember that a Notice of Termination and new Notice of Intent are required whenever a facility operation is relocated or changes ownership.

If you have any questions, please contact your Regional Board Industrial Storm Water Permit Contact. The names, telephone numbers, and e-mail addresses of the Regional Board contacts, as well as the Regional Board office addresses, can be found at:

[http://www.waterboards.ca.gov/water\\_issues/programs/stormwater/contact.shtml](http://www.waterboards.ca.gov/water_issues/programs/stormwater/contact.shtml)

### General Information

#### A. Facility Information

WDID: 7 361019443

Business Name: PGE Topock Interim Measure No 3

Physical Address: I 40 and Park Moabi Rd

City: Needles

Contact Person: Chris Smith

State: CA

Phone: 760-258-7899

Zip: 92363

Email: [cks5@pge.com](mailto:cks5@pge.com)

Standard Industrial Classification (SIC) Codes: 4953-Refuse Svstems

#### B. Facility Owner Information

Business Name: Pacific Gas Electric Co

Mailing Address: PO Box 337

City: Needles

Contact Person: Christopher Smith

State: CA

Phone: 760-258-7899

Zip: 92363

Email: [cks5@pge.com](mailto:cks5@pge.com)

#### C. Facility Billing Information

Business Name: Pacific Gas Electric Company San Francisco

Mailing Address: PO BOX 337

City: Needles

Contact Person: Glen Curtis Russell

State: CA

Phone: 760-791-5884

Zip: 92363

Email: [acr4@pge.com](mailto:acr4@pge.com)

## Question Information

1. Has the Discharger conducted monthly visual observations (including authorized and unauthorized Non-Storm Water Discharges and Best Management Practices) in accordance with Section XI.A.1?

Yes       No

If No, see Attachment 1, Summary of Explanation.

2. Has the Discharger conducted sampling event visual observations at each discharge location where a sample was obtained in accordance with Section XI.A.2?

Yes       No

If No, see Attachment 1, Summary of Explanation.

3. Did you sample the required number of Qualifying Storm Events during the reporting year for all discharge locations, in accordance with Section XI.B?

Yes       No

If No, see Attachment 1, Summary of Explanation.

4. How many storm water discharge locations are at your facility?

5

5. Has the Discharger chosen to select Alternative Discharge Locations in accordance with Section XI.C.3?

Yes       No

6. Has the Discharger reduced the number of sampling locations within a drainage area in accordance with the Representative Sampling Reduction in Section XI.C.4?

Yes       No

6.1. Has the Discharger reduced the frequency of sampling at the facility area in accordance with the Sample Frequency Reduction in Section XI.C.7?

Yes       No

7. Permitted facilities located within an impaired watershed must assess for potential pollutants that may be present in the facility's industrial storm water discharge. Using the table below, populated based on the facility's location, indicate the presence of the potential pollutant at the facility.

The facility is not located within an impaired HUC 10 watershed. You are not required to select any Industrial Pollutants. Skip Questions 8 and 9.

8. Has the Discharger included the above pollutants in the SWPPP pollutant source assessment and assessed the need for analytical monitoring for the pollutants?

Yes       No

If No, what date will the parameter(s) will be added to the SWPPP and Monitoring Implementation Plan?

9. Were all samples collected in accordance with Section XI.B.5?

Yes       No

If No, see Attachment 1, Summary of Explanation.

10. Has any contained storm water been discharged from the facility this reporting year?

Yes       No

If Yes, see Attachment 1, Summary of Explanation.

11. Has the Discharger conducted one (1) annual evaluation during the reporting year as required in Section XV?

Yes       No

If Yes, what date was the annual evaluation conducted?    05/31/2018

If No, see Attachment 1, Summary of Explanation.

12. Has the Discharger maintained records on-site for the reporting year in accordance with XXI.J.3?

Yes       No

If No, see Attachment 1, Summary of Explanation.

If your facility is subject to Effluent Limitation Guidelines in Attachment F of the Industrial General Permit, include your specific requirements as an attachment to the Annual Report (attach as file type: Supporting Documentation).

## ANNUAL REPORT CERTIFICATION

I certify under penalty of law that this document and all attachments were prepared under the direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Printed Name: Glen Russell

Title: Site Operations Manager

Date: 06/26/2018

**Annual Report for WDID 7 36I019443****Summary of Explanations**

<b>Explanation Question</b>	<b>Explanation Text</b>
Question 2	There were no storm events that resulted in discharge of stormwater from the site during the July 1, 2017 through June 30, 2018 period; therefore, no stormwater samples were collected. In general, discharge of stormwater from the facility did not occur due to the arid climate, drainage properties of soil at unpaved areas, and pumping of storm water collected on the concrete treatment pad into the treatment facility. During rain events, when safe, the site was walked to observe and monitor discharge locations.
Question 3	There were no storm events that resulted in discharge of stormwater from the site during the July 1, 2017 through June 30, 2018 period; therefore, no stormwater samples were collected. In general, discharge of stormwater from the facility did not occur due to the arid climate, drainage properties of soil at unpaved areas, and pumping of storm water collected on the concrete treatment pad into the treatment facility. During rain events, when safe, the site was walked to observe and monitor discharge locations.
Question 9	There were no storm events that resulted in discharge of stormwater from the site during the July 1, 2017 through June 30, 2018 period; therefore, no stormwater samples were collected. In general, discharge of stormwater from the facility did not occur due to the arid climate, drainage properties of soil at unpaved areas, and pumping of storm water collected on the concrete treatment pad into the treatment facility. During rain events, when safe, the site was walked to observe and monitor discharge locations.

**Summary of Attachments**

<b>Attachment Type</b>	<b>Attachment Title</b>	<b>Description</b>	<b>Date Uploaded</b>	<b>Part Number</b>	<b>Attachment Hash</b>
------------------------	-------------------------	--------------------	----------------------	--------------------	------------------------

2017-2018

**Annual Report for WDID 7 36I019443**

**List of Identified Pollutants within the Impaired Watershed**

Parameter	Pollutant	Present at Facility?
-----------	-----------	----------------------